

PressurePro Intensive Deep Cleaner RM 750

Powerful deep cleaner effectively removes the most stubborn stains, such as oil, grease, soot, blood and proteins. Low foam production. Particularly suited for floor cleaning by machine and for processing with hard surface cleaners.

pH value 14
in concentrate



Properties

- Intensive basic cleaner for use with high-pressure and floor cleaning units
- For deep cleaning of heavily soiled industrial floor coverings
- Loosens heavy oil, grease and mineral-based soiling
- Rapidly effective
- Low-foam formulation
- Extremely economical
- Tensides biodegradable in accordance with EEC 648/2004
- Quick oil and water separation in the oil separator (easily separable = asf)
- NTA-free

Usage options

- High-pressure cleaners
- Scrubber driers
- Manual

Application areas

Agriculture	Transport and machines
Car dealership and garage	Car/engine wash, Parts cleaning
Building Industry	Transport and machines
Building cleaning	Floor cleaning
Food and drink industry	Floor cleaning
Industry	Surface degreasing
Municipal	Car/engine wash
Retail	Floor cleaning
Haulage contractors, bus operators	Car/engine wash

Technical data

Container sizes	Packaging unit	Part number
10 l	1 Piece(s)	6.295-539.0
200 l	1 Piece(s)	6.295-540.0

Application

High-pressure cleaners

- Apply primary mixture with fresh water.
- Set the dosage and temperature on the device
- 1-80°C processing temperature.
- Clean object.
- Rinse surface well with clear water.

Scrubber-driers – deep cleaning

- Combine the product with the appropriate dosage and fresh water.
- Allow to soak.
- Contact time 10-15 minutes, depending on the degree of soiling.
- Wet object completely with the product.
- Clean the surface in overlapping sections.
- Neutralise with clear water.

Manual

- Combine the product with the appropriate dosage and fresh water.
- Allow to soak.
- Contact time 10-15 minutes, depending on the degree of soiling.
- Wet object completely with the product.
- Incorporate the cleaning fluid.
- Neutralise with clear water.



Instructions for use

- Test on an inconspicuous part for material compatibility.
- Do not let the cleaning solution dry out.

Warnings and safety recommendations according to EC Directives

- Danger
- H290 May be corrosive to metals
- H314 Causes severe skin burns and eye damage
- P280 Wear protective gloves/protective clothing/eye protection/face protection.
- P305 + P351 + P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
- P310 Immediately call a POISON CENTER/doctor.
- P303 + P361 + P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower].
- P405 Store locked up.
- P501a Dispose of contents/container in accordance with local/regional/national/international regulations.

Further information

- Material Safety Data Sheet (MSDS)

Dosage and yield

Contents	Cleaning method	Primary mixture	Dosage	Soiling	Yield
1000 ml	High-pressure cleaners	1+3	1 – 5 %	strong	270 m ²
1000 ml	Scrubber driers – Stripping		10 – 50 %	strong	110 m ²
1000 ml	Scrubber-driers – deep cleaning		5 – 50 %	strong	370 m ²
1000 ml	Scrubber driers – maintenance cleaning		1 – 5 %	mild-medium	3300 m ²
1000 ml	Manual		5 – 50 %	strong	120 m ²